

NJPIA TRAINING TRACKER



MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Allen Feid, Jr.</i>					
7052	8160	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
1925	7699	0000	Unintended Consequences of Low Flow Fixtures and Faucets	1/20/2016	1
7052	8160	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
<i>Andrew Guarrera</i>					
11806	10481	2190	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11806	10481	2190	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Anthony Gargani</i>					
6237	6110	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6237	6110	0000	Venting For All Types of Boilers	10/21/2015	1
6237	6110	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Bernard Reilly</i>					
7096	4815	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7096	4815	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
7096	4815	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
7096	4815	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7096	4815	0000	Code Answers to Code Questions	3/16/2016	1
7096	4815	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Calvin King</i>					
5000	5150	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5000	5150	0000	Significant Changes to ANSI A117.1	9/16/2015	1
5000	5150	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
5000	5150	6987	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
5000	5150	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
5000	5150	6987	Code Answers to Code Questions	3/16/2016	1
5000	5150	6987	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Charles Miuccio</i>					
5967	5967	1990	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5967	5967	1990	Code Answers to Code Questions	3/16/2016	1
<i>Charles West</i>					
6935	10202	0722	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6935	10202	0722	Significant Changes to ANSI A117.1	9/16/2015	1
6935	10202	0722	In-Depth Venting Methods For Boilers	10/21/2015	1
6935	10202	0722	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6935	10202	0722	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6935	10202	0722	Code Answers to Code Questions	3/16/2016	1
<i>Daniel O'Gorman</i>					
7656	4509	3966	Significant Changes to ANSI A117.1	9/16/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>David Bishop</i>					
8179	7572	2939	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8179	7572	2939	Significant Changes to ANSI A117.1	9/16/2015	1
8179	7572	2939	In-Depth Venting Methods For Boilers	10/21/2015	1
8179	7572	2939	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8179	7572	2939	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8179	7572	2939	Code Answers to Code Questions	3/16/2016	1
8179	7572	2939	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>David Daffeldeker</i>					
11924	7255	3221	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
11924	7255	3221	Significant Changes to ANSI A117.1	9/21/2015	1
11924	7255	3221	In-Depth Venting Methods For Boilers	10/21/2015	1
11924	7255	3221	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/2/2016	1
11924	7255	3221	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11924	7255	3221	Code Answers to Code Questions	3/16/2016	1
11924	7255	3221	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Dennis Gibson</i>					
6777	10249	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6777	10249	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6777	10249	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Dennis Goldenbaum</i>					
9298	8571	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
9298	8571	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
9298	8571	0000	Code Answers to Code Questions	3/16/2016	1
<i>Dominic Demico</i>					
5716	7868	0105	Significant Changes to ANSI A117.1	9/16/2015	1
5716	7868	0105	Code Answers to Code Questions	3/16/2016	1
<i>Dominic Demico, Jr.</i>					
7051	6236	0103	Significant Changes to ANSI A117.1	9/16/2015	1
7051	6236	0103	Significant 2015 Code Changes	9/17/2015	1
<i>Don Macniven</i>					
0000	7320	0000	Significant Changes to ANSI A117.1	9/16/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Edward Frey, Jr.</i>					
4324	421	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
4324	421	0000	Code Answers to Code Questions	3/16/2016	1
<i>Errol Lamberson</i>					
5119	475	1949	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5119	475	1949	Significant Changes to ANSI A117.1	9/16/2015	1
5119	475	1949	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
5119	475	1949	Code Answers to Code Questions	3/16/2016	1
5119	475	1949	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Frank Kneipher</i>					
0	7852	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
0	7852	0000	Significant Changes to ANSI A117.1	9/16/2015	1
0	7852	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
0	7852	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
0	7852	0000	Code Answers to Code Questions	3/16/2016	1
0	7852	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Frank Nocito</i>					
7068	9430	1516	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7068	9430	1516	Significant Changes to ANSI A117.1	9/16/2015	1
7068	9430	1516	In-Depth Venting Methods For Boilers	10/21/2015	1
7068	9430	1516	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
7068	9430	1516	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7068	9430	1516	Code Answers to Code Questions	3/16/2016	1
7068	9430	1516	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Frank Speranza</i>					
7849	8358	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7849	8358	0000	Significant Changes to ANSI A117.1	9/16/2015	1
7849	8358	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
7849	8358	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7849	8358	0000	Code Answers to Code Questions	3/16/2016	1
7849	8358	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Frank Verange</i>					
6260	5374	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6260	5374	0000	Significant Changes to ANSI A117.1	9/16/2015	1
6260	5374	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
6260	5374	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6260	5374	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6260	5374	0000	Code Answers to Code Questions	3/16/2016	1
6260	5374	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Gary Bertolo</i>					
0000	3498	0000	Significant Changes to ANSI A117.1	9/16/2015	1
0000	3498	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
0000	3498	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
0000	3498	0000	Code Answers to Code Questions	3/16/2016	1
0000	3498	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Gary Maffetone</i>					
6417	3953	3357	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6417	3953	3357	Significant Changes to ANSI A117.1	9/16/2015	1
6417	3953	3357	In-Depth Venting Methods For Boilers	10/21/2015	1
6417	3953	3357	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6417	3953	3357	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>George Boral</i>					
8026	7786	3304	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	0
<i>George Duemmer</i>					
1623	678	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
<i>Guisseppi La Mastra</i>					
7692	8015	5134	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7692	8015	5134	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7692	8015	5134	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Henry Salerno</i>					
5193	2000	1243	Significant Changes to ANSI A117.1	9/16/2015	1
5193	2000	1243	In-Depth Venting Methods For Boilers	10/21/2015	1
5193	2000	1243	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
5193	2000	1243	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
5193	2000	1243	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
5193	2000	1243	Code Answers to Code Questions	3/16/2016	1
5193	2000	1243	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Herbert Moore</i>					
989	2045	0000	In-Depth Venting Methods For Boilers	10/21/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Jack Minervi</i>					
4710	5508	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
4710	5508	0000	Significant Changes to ANSI A117.1	9/16/2015	1
4710	5508	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
4710	5508	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
4710	5508	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
4710	5508	0000	Code Answers to Code Questions	3/16/2016	1
4710	5508	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>James DeForte</i>					
8312	8538	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8312	8538	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8312	8538	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8312	8538	0000	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>James Wulfekotte</i>					
7272	7925	0000	Significant Changes to ANSI A117.1	9/16/2015	1
7272	7925	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
7272	7925	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
7272	7925	0000	Code Answers to Code Questions	3/16/2016	1
7272	7925	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>John Randazzo</i>					
11666	10889	6423	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
<i>John Sheridan</i>					
4662	4662	2111	In-Depth Venting Methods For Boilers	10/21/2015	1
4662	4662	2111	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	0
4662	4662	2111	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
4662	4662	2111	Code Answers to Code Questions	3/16/2016	1
<i>Joseph Albanese</i>					
6622	5573	0000	Significant 2015 Code Changes	11/18/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Joseph Crane</i>					
0000	6919	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
0000	6919	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Joseph Di Rosa</i>					
6464	8183	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6464	8183	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
6464	8183	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6464	8183	0000	Code Answers to Code Questions	3/16/2016	1
6464	8183	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Joseph Gandolfo</i>					
8749	9878	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Joseph Penevolpe</i>					
6303	8200	5119	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6303	8200	5119	Significant Changes to ANSI A117.1	9/16/2015	1
6303	8200	5119	In-Depth Venting Methods For Boilers	10/21/2015	1
6303	8200	5119	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6303	8200	5119	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6303	8200	5119	Code Answers to Code Questions	3/16/2016	1
6303	8200	5119	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Joseph Scaramuzzo</i>					
6090	5842	1739	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6090	5842	1739	Significant Changes to ANSI A117.1	9/16/2015	1
6090	5842	1739	In-Depth Venting Methods For Boilers	10/21/2015	1
6090	5842	1739	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6090	5842	1739	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/10/2016	1
6090	5842	1739	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Keith Will</i>					
11768	9871	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
11768	9871	0000	Significant Changes to ANSI A117.1	9/16/2015	1
11768	9871	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
11768	9871	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11768	9871	7457	Code Answers to Code Questions	3/16/2016	1
11768	9871	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Leigh Hopper</i>					
2243	3707	0000	Significant Changes to ANSI A117.1	9/16/2015	1
2243	3707	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
2243	3707	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
2243	3707	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
2243	3707	0000	Code Answers to Code Questions	3/16/2016	1
2243	3707	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Leon Fortin</i>					
988	1239	0000	Significant Changes to ANSI A117.1	9/17/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Liri Miftari</i>					
12027	9791	2502	Code Answers to Code Questions	3/16/2016	1
12027	9791	2502	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Louis Buonocore</i>					
10237	7670	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
10237	7670	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
10237	7670	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
10237	7670	0000	Code Answers to Code Questions	3/16/2016	1
10237	7670	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Mark Bocchino</i>					
8250	8674	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8250	8674	0000	Significant Changes to ANSI A117.1	9/16/2015	1
8250	8674	6929	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8250	8674	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8250	8674	0000	Code Answers to Code Questions	3/16/2016	1
8250	8674	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Mark Hiler</i>					
5353	4132	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5353	4132	0000	Significant Changes to ANSI A117.1	9/16/2015	1
5353	4132	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
<i>Marvin Carman</i>					
2216	3676	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
2216	3676	0000	Significant Changes to ANSI A117.1	9/16/2015	1
2216	3676	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
2216	3676	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
2216	3676	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
2216	3676	0000	Code Answers to Code Questions	3/16/2016	1
2216	3676	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Michael Baker</i>					
6964	8133	0000	Significant Changes to ANSI A117.1	9/16/2015	1
6964	8133	0000	Significant 2015 Code Changes	9/17/2015	1
6964	8133	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
6964	8133	0000	Code Answers to Code Questions	1/13/2016	1
6964	8133	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Michael Brown</i>					
11273	10559	2828	Significant Changes to ANSI A117.1	9/16/2015	1
11273	10559	2828	In-Depth Venting Methods For Boilers	10/21/2015	1
11273	10559	2828	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
<i>Michael Daley</i>					
7377	9592	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7377	9592	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7377	9592	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Michael Krupsky</i>					
8486	7694	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8486	7694	0000	Significant Changes to ANSI A117.1	9/16/2015	1
8486	7694	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
8486	7694	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8486	7694	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8486	7694	0000	Code Answers to Code Questions	3/16/2016	1
8486	7694	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Michael Primak</i>					
8405	7936	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8405	7936	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8405	7936	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Neil Brooks</i>					
8551	9580	2244	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8551	9580	2244	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8551	9580	2244	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8551	9580	2244	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Nick Azmo</i>					
9919	7347	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
9919	7347	0000	Significant Changes to ANSI A117.1	9/16/2015	1
9919	7347	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
9919	7347	6991	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
9919	7347	6991	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
9919	7347	6991	Code Answers to Code Questions	3/16/2016	1
<i>Norm Dobo</i>					
8894	5739	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Patrick Duggan</i>					
11000	10851	3359	Significant Changes to ANSI A117.1	9/16/2015	1
11000	10851	3359	In-Depth Venting Methods For Boilers	10/21/2015	1
11000	10851	3359	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Peter Simchera</i>					
5021	5861	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5021	5861	0000	Significant Changes to ANSI A117.1	9/16/2015	1
5021	5861	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
5021	5861	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
5021	5861	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
5021	5861	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
5021	5861	0000	Code Answers to Code Questions	3/16/2016	1
5021	5861	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Raymond Keeley</i>					
10450	10919	3775	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Richard Adams</i>					
7718	5908	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7718	5908	0000	Significant Changes to ANSI A117.1	9/16/2015	1
7718	5908	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
7718	5908	0000	Significant 2015 Code Changes	11/18/2015	1
7718	5908	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
7718	5908	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7718	5908	0000	Code Answers to Code Questions	3/16/2016	1
7718	5908	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Richard Beard</i>					
10624	10423	4453	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
10624	10423	0000	Significant Changes to ANSI A117.1	9/16/2015	1
10624	10423	4453	In-Depth Venting Methods For Boilers	10/21/2015	1
10624	10423	4453	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
10624	10423	4453	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Richard Riople</i>					
7554	6842	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7554	6842	0000	Code Answers to Code Questions	3/16/2016	1
<i>Robbie Bailey</i>					
10052	10217	4139	In-Depth Venting Methods For Boilers	10/21/2015	1
10052	10217	4139	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
10052	10217	4139	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
10052	10217	4139	Code Answers to Code Questions	3/16/2016	1
10052	10217	4139	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Robert Hartsgrove</i>					
6603	7755	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6603	7755	0000	Significant Changes to ANSI A117.1	9/16/2015	1
6603	7755	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
6603	7755	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6603	7755	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6603	7755	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Robert Kelly, Jr.</i>					
10222	10148	0813	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
10222	10148	0813	Significant Changes to ANSI A117.1	9/16/2015	1
10222	10148	0813	In-Depth Venting Methods For Boilers	10/21/2015	1
10222	10148	0813	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
10222	10148	0813	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
10222	10148	0813	Code Answers to Code Questions	3/16/2016	1
<i>Robert Kleiberg</i>					
8791	7889	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8791	7889	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8791	7889	0000	Significant Changes to ANSI A117.1	9/16/2015	1
8791	7889	0000	Significant 2015 Code Changes	9/17/2015	1
8791	7889	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
8791	7889	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8791	7889	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8791	7889	0000	Code Answers to Code Questions	3/16/2016	1
8791	7889	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Robert Muller</i>					
7053	10667	4852	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7053	10667	4852	Significant Changes to ANSI A117.1	9/16/2015	1
<i>Robert Nelson</i>					
11021	10073	1057	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
11021	10073	1057	Significant Changes to ANSI A117.1	9/16/2015	1
11021	10073	1057	In-Depth Venting Methods For Boilers	10/21/2015	1
11021	10073	1057	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
11021	10073	1057	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11021	10073	1057	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Robert Wennlund</i>					
8064	4580	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8064	4580	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
8064	4580	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8064	4580	0000	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Ronald Barbarulo</i>					
8978	9477	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
8978	9477	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8978	9477	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8978	9477	0000	Code Answers to Code Questions	3/16/2016	1
8978	9477	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Ronald Bauer</i>					
1428	1824	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
1428	1824	0000	Significant Changes to ANSI A117.1	9/16/2015	1
1428	1824	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
1428	1824	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
1428	1824	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
1428	1824	0000	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Ronald Veiss</i>					
4185	1053	0000	Significant Changes to ANSI A117.1	9/16/2015	1
4185	1053	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
4185	1053	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
4185	1053	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Russell Hall</i>					
8831	8609	0000	Significant Changes to ANSI A117.1	9/16/2015	1
8831	8609	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
8831	8609	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
8831	8609	0000	Code Answers to Code Questions	3/16/2016	1
8831	8609	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Sal Farruggia</i>					
10689	8406	0000	Significant Changes to ANSI A117.1	9/16/2015	1
10689	8406	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	0
10689	8406	0000	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Sam De Padova</i>					
995	235	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
995	235	0000	Significant Changes to ANSI A117.1	9/16/2015	1
995	235	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
995	235	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
995	235	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
995	235	0000	Code Answers to Code Questions	3/16/2016	1
995	235	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Sergio Amoedo</i>					
12282	10684	0183	In-Depth Venting Methods For Boilers	10/21/2015	1
12282	10684	0183	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
12282	10684	0183	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
12282	10684	0183	Code Answers to Code Questions	3/16/2016	1
12282	10684	0183	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Stephen Germann II</i>					
11997	8475	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
11997	8475	0000	Significant Changes to ANSI A117.1	9/16/2015	1
11997	8475	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
11997	8475	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
11997	8475	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11997	8475	0000	Code Answers to Code Questions	3/16/2016	1
<i>Stephen Rodzinak</i>					
6761	8587	0167	Significant 2015 Code Changes	11/18/2015	1
<i>Steve Rickershauser</i>					
7383	3786	1640	Significant 2015 Code Changes	11/18/2015	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Thomas F. Walsh</i>					
7854	5634	1568	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
7854	5634	1568	In-Depth Venting Methods For Boilers	10/21/2015	1
7854	5634	1568	Significant 2015 Code Changes	11/18/2015	1
7854	5634	1568	Significant 2015 Code Changes	11/18/2015	1
7854	5634	1568	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
7854	5634	1568	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
7854	5634	1568	Code Answers to Code Questions	3/16/2016	1
7854	5634	1568	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Thomas Mc Gonigle</i>					
4586	838	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
4586	838	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
4586	838	0000	Significant Changes to ANSI A117.1	10/26/2015	1
4586	838	0000	Significant 2015 Code Changes	11/18/2015	1
4586	838	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
4586	838	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
4586	838	0000	Code Answers to Code Questions	3/16/2016	1
4586	838	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Thomas Pitcherello</i>					
0000	4398	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
0000	4398	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
0000	4398	0000	Significant 2015 Code Changes	11/18/2015	1
0000	4398	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
0000	4398	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
0000	4398	0000	Code Answers to Code Questions	3/16/2016	1
0000	4398	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Thomas Polino</i>					
9804	7938	0000	Significant 2015 Code Changes	11/18/2015	1
<i>Thomas Winch</i>					
11672	10785	1770	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
11672	10785	1770	Significant Changes to ANSI A117.1	9/16/2015	1
11672	10785	1770	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
11672	10785	1770	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
11672	10785	1770	Code Answers to Code Questions	3/16/2016	1
11672	10785	1770	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>Timothy Skinner</i>					
0000	9402	0000	Significant Changes to ANSI A117.1	9/16/2015	1
<i>Vincent Tinervia</i>					
10945	10733	0163	Significant Changes to ANSI A117.1	9/16/2015	1
10945	10733	0163	In-Depth Venting Methods For Boilers	10/21/2015	1
10945	10733	0163	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
10945	10733	0163	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
10945	10733	0163	Code Answers to Code Questions	3/16/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>Warren Winch</i>					
6488	10928	3050	Significant Changes to ANSI A117.1	9/16/2015	1
6488	10928	3050	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
6488	10928	3050	Code Answers to Code Questions	3/16/2016	1
<i>Werner Heinemann</i>					
6406	9850	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
6406	9850	0000	In-Depth Venting Methods For Boilers	10/21/2015	1
6406	9850	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
6406	9850	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1
<i>William Olinger</i>					
5054	2318	0000	Unintended Consequences of Low Flow Fixtures and Faucets	6/17/2015	1
5054	2318	0000	Significant Changes to ANSI A117.1	9/16/2015	1
5054	2318	0000	Significant 2015 Code Changes	11/18/2015	1
5054	2318	0000	CSST Bonding Regarding ANSI 1024 & ANSI 1027 Standards	1/20/2016	1
5054	2318	0000	Statutes & Regulations For Master Plumbers and HVACR Contractors	2/17/2016	1
5054	2318	0000	Code Answers to Code Questions	3/16/2016	1
5054	2318	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1

MASTER PLUMBER	CODE OFFICIAL	MASTER HVACR	CLASS NAME	CLASS DATE	HOURS
<i>William Roman</i>					
10248	9365	0000	Significant Changes to ANSI A117.1	9/16/2015	1
10248	9365	0000	Code Answers to Code Questions	3/16/2016	1
10248	9365	0000	Cast Iron Soil Pipe Standards and Installation Specs	4/20/2016	1